




1300 SUMNER AVENUE, CLEVELAND, OHIO 44115-2851 216-241-7333 FAX 216-241-0105

E-Mail: [pti@powertoolinstitute.com](mailto:pti@powertoolinstitute.com) URL: [www.powertoolinstitute.com](http://www.powertoolinstitute.com)

## **PTI LAB TEST PROCEDURE FOR DETERMINING STATED RELATIVE TORQUE MEASUREMENT FOR CORDED AND CORDLESS DRILLS, DRILL/DRIVERS, AND SCREWDRIVERS**



### **1.0 PURPOSE**

The purpose of this document is to define a common method for measuring a relative output torque.

### **2.0 SCOPE**

This procedure applies to all corded and cordless drills, drill/drivers, and screwdrivers not intended for assembly/production use. It does not apply to products employing impacting devices such as hammer drills, rotary hammers and impact drivers. The Relative Torque Measurement (RTM) determined in accordance with this document represents the output torque developed by the product under test with a 95% confidence. The RTM is obtained under laboratory test conditions and is intended for use in comparing similar products. The actual output torque generated by an individual sample may vary slightly. The RTM should not be interpreted as a statement of the product's performance when used for precision fastening operations or in applications where tightening is specified.

### **3.0 GENERAL CONDITIONS FOR THE TESTS**

**3.1** Tests according to this procedure are type tests.

**3.2** The test is made on a total of five normal production samples which have not been modified. The test consists of five trials on each sample.

*Additional samples shall be used for testing at different supply voltages.*

- 3.3** Tools provided with controls or switching devices are tested with these controls or devices adjusted to their setting which generates the highest torque.

If the adjusting means of the control is accessible without the aid of a tool, this subclause applies whether the setting can be altered by hand or with the aid of a tool. If the adjusting means is not accessible without the aid of a tool, and if the setting is not intended to be altered by the user, this subclause does not apply.

- 3.4** The tests are made in a draught-free location and at an ambient temperature of 20 ( $\pm$  5) °C.

- 3.5** Tools having more than one rated voltage are tested for all rated voltages. The RTM for a tool tested at a specific voltage only applies to that tool/voltage unless otherwise confirmed by testing.

- 3.6** For cordless tools, all testing shall be performed with conditioned battery packs. Conditioning shall consist of five charges and five discharges for each battery pack sample used during testing. Charging shall be performed with the appropriate charger recommended by the manufacturer for the battery pack under test, or a suitable device capable of duplicating the charger function. For Ni-Cd and Ni-Mh, discharging shall consist of a 10c discharge rate to .9 volts per cell. For Li-ion, discharging should consist of a 10c discharge rate or as recommended by the cell manufacturer to 2.7 volts per cell.

**3.6.1** Using a previously conditioned battery pack, from 3.6, the battery pack is to be charged, allowed to cool to room temperature and then discharged for a period of 4 minutes with a resistive load determined as follows:  $V/(5C)$  ohm (where V is the voltage of the battery stated by the manufacturer and c is the manufacturer's stated ampere-hour rating of the battery pack. Allow the sample to return to room temperature prior to testing.

**3.6.2** Unless otherwise specified, a battery pack as prepared in accordance with 3.6 and 3.6.1 shall be used for each cordless tool test.

- 3.7** For corded tools, all testing shall be performed with a regulated power supply circuit which provides the nominal voltage and frequency provided on the tool's nameplate (e.g. 120 volts ac 60 Hz). The power supply circuit shall also be suitably sized to withstand the stall current of the unit under test.

- 3.8** For corded tools, all relevant normally-supplied motor and electric power supply components such as the power cord, switch, speed controls, etc. shall be in the circuit, so that normal power losses in the tool are reflected by the measurement.

## **4.0 PROCEDURE**

### **4.1 Setup**

**4.1.1** The test sample shall be supported to prevent tool movement due to reactionary torque. In addition the tool shall be supported so that it can be fed inward toward the rundown adapter. This will insure that the operator does not absorb the energy from the sample during testing. See Section 5 for a typical test fixture.

**4.1.2** If the test sample has an adjustable clutch, the clutch should be set in the full-lock position. If the tool clutch slips during testing, the results are considered to be invalid.

**4.1.3** If the tool is equipped with various gear ranges, set the tool to the gear range which results in the greatest torque value.

**4.1.4** If the test sample has forward and reverse rotation, set the rotation in the forward position. Torque shall always be measured in the forward position.

**4.1.5** Either a cordless tool having a battery pack that is prepared in accordance with 3.6.1, or a corded tool connected to a power supply circuit in accordance with 3.7, shall be mounted on the fixture.

**4.1.6** The test sample shall now be connected to a model 10002-I-ETT (electronic torque tester) manufactured by CDI Torque Products. In addition, a joint rate simulator adaptor shall be placed between the output of the test sample and the torque tester. The lowest capacity joint rate simulator shall be used which will measure the expected maximum output torque of the tool. CDI Torque Products offers the following three sizes to choose from:

Model 900-0-KIT – capacity 50 in. lbs.

Model 900-2-01KIT – capacity 400 in. lbs.

Model 900-3-01KIT – capacity 1000 in. lbs.

## **4.2 Testing**

**4.2.1** Manually energize the test sample as quickly as possible by actuating the switch to the full on position. This action should represent normal use. Allow the joint rate simulator to tighten until it comes to a complete stop. Record the output torque.

**4.2.2** Allow the test sample to cool a minimum of three minutes before performing the next trial. This will allow the test sample to cool prior to the next measurement, and insure more consistent readings.

**4.2.3** Repeat steps 4.2.1 and 4.2.2 for a total of five trials. For cordless tools, utilize the same battery pack or sample for the five trials without recharging.

**4.2.4** Repeat steps 4.2.1 through 4.2.3 on four additional samples.

### 4.3 Calculations

Background: The following statistical analysis of the recorded data serves as a method to determine the RTM of the tool with a 95% confidence.

**4.3.1** Once all twenty-five trials have been completed, the average torque value of the trials, the standard deviation for the trials, and the high and low data point limits shall be calculated by following the equations:

$$\text{Average Torque, } T_{\text{avg}} = \sum(T_i)/n \quad \text{eq.1}$$

$$\text{Sample standard deviation calculated by } s = \sqrt{\sum (T_i - T_{\text{avg}})^2 / (n-1)} \quad \text{eq.2}$$

$$\text{High data point limit} = T_{\text{avg}} + (2*s) \quad \text{eq.3}$$

$$\text{Low data point limit} = T_{\text{avg}} - (2*s) \quad \text{eq.4}$$

Where:  $T_i$  is the measure torque value for the  $i^{\text{th}}$  trial

$T_{\text{avg}}$  is the average of the measured torque values for the 25 trials

$n$  is the number of trials, given to be 25.

**4.3.2** The test data should then be reviewed to ensure the measured torque value for each trial is within 2 standard deviations of the average value,  $T_{\text{avg}}$ . For any test sample which generates a test value that is outside of these limits, the data from that sample shall be discarded, steps 4.2.1-4.2.3 shall be performed on another sample, and the above values re-calculated. This process shall be repeated until all data points meet the requirements of this 4.3.2.

**4.3.3** Once all test values are determined to be acceptable, the 95% confidence limits for the data are to be calculated

$$\text{Lower 95\% Confidence Limit, } LCL = T_{\text{avg}} - t_c(s/\sqrt{n}) \quad \text{eq.5}$$

$$\text{Upper Confidence Limit, } UCL = T_{\text{avg}} + t_c(s/\sqrt{n}) \quad \text{eq.6}$$

Where:  $t_c$  is the 95% confidence t-distribution factor, given to be 2.06

**4.3.4** Based on a 95% confidence, the value of the output torque will be between the LCL and UCL. The RTM shall be the LCL as there is 95% confidence the actual maximum torque value will be at least this value when tested to this procedure.